



Quality assurance for the DØ silicon tracker



- Run2, DØ and the silicon tracker
- Quality assurance during production
 - sensors
 - chips/ flex circuits
 - ladders
 - system tests
- Concluding remarks


Frank Lehner
U of Zurich/ Fermilab
On behalf of the
DØ Collaboration

First $p\bar{p}$ collision at DØ

April 3, 2001

- Luminosity counters

- timing:





Antiproton halo

Luminosity
(coincidence)
 $\sim 5 \times 10^{27} \text{ cm}^{-2} \text{ sec}^{-1}$


Proton halo

Vertex distribution along z
of min bias events:

Run2 has started with
an upgraded detector:



The DØ silicon tracker





- 6 barrels, 4 layers of silicon, interspersed F-disks, design driven by large interaction region ($\sigma=25\text{cm}$) w/ good acceptance for high p_t tracks
- large area external H-disks for forward tracking $2<|\eta|<3$
- Detector & inboard electronics moderately rad-hard (4MRad)

	Barrels	F-Disks	H-Disks
Channels	387120	258048	147456
Modules	432	144	96
Inner R	2.7 cm	2.6 cm	9.5 cm
Outer R	9.4 cm	10.5 cm	26 cm

total 793,000 channels !!

The DØ silicon tracker



- silicon tracker has been built within 18 months:
 - formidable production job
 - ✓ tested and assembled ~1400 silicon pieces with a total wafer area of 3.2m² to build more than 800 ladders
 - ✓ debugged & repaired ladders
 - ✓ placed ladders into barrels and wedges onto disks
 - ✓ assembled barrels/disks to two half detectors
 - ✓ inserted two halves into DØ




Sensor types



- 5 different sensor types:
 - **Barrels:**
 - ✓ double sided with 2°-stereo strips, pitch 50μm on p-side, 62.5μm on n-side, AC-coupled, polysilicon bias on 4"-wafers
 - ✓ double sided with 90°-stereo strips and double metal layer, pitch 50μm on p-side and 153μm on n-side, AC-coupled, polysilicon bias on 6"-wafers
 - ✓ single sided with 50μm pitch, AC-coupled and polysilicon on 4"-wafers
 - **Disks:**
 - ✓ double sided wedges with ±15° variable strip length, AC-coupled and polysilicon on 4"-wafers
 - ✓ single sided wedges glued back to back with ±7.5°
 - Main vendors: Micron/UK, ELMA and Eurisys
- Total amount: ~1400 sensors



Sensor specifications



- wafer thickness $300 \pm 20 \mu\text{m}$
- leakage current $< 0.5 \mu\text{A}/\text{cm}^2$ @ $2U_{\text{depl}}$
- breakdown voltage $> 100\text{V}$
- depletion voltage $20 < U_{\text{depl}} < 60\text{V}$
- bias resistor R_{bias}
 - $1 < R_{\text{bias}} < 10\text{M}\Omega$
 - uniformity better than $\pm 25\%$
- interstrip resistance $> 100\text{M}\Omega$
- coupling capacitors
 - $\sim 15\text{pF}/\text{cm}$
 - channels outside $\pm 15\%$ fail
 - coupling capacitor breakdown 100V for both sides n/p
- interstrip capacitance $< 1.5\text{pF}/\text{cm}$
- bad channels (short, open, pinhole)
 - generally 2%
 - 4% in case of n-side with double-metal layer
- specs lowered during sensor prod. in order to achieve higher deliv. rate



Sensor quality assurance



- originally planned:
 - have probe testing of production sensors at vendor and to test only small samples at Fermilab/Universities as cross check
- did not work as anticipated:
 - discrepancies of measurements, reliability of testing at vendor, short manpower at vendor, low delivery rates with double sided detectors
- decided to send own probe equipment and manpower to main vendor:
 - had for more than 20 months own technician(s)+equipment locally present to test F-disks and 2^o-stereo sensors
 - set up 2 automatic probe station at vendor
 - local presence improved a lot
 - ✓ reliable acceptance testing
 - ✓ immediate feedback to process engineer
 - ✓ overall increase of delivery rates
 - due to its complexity the double-sided double-metal sensors were locally tested by Micron personnel and retested at Fermilab

Sensor probing


- measured on manual/automatic probe station on each sensor:
 - C-V $\Rightarrow U_{\text{depl}}$
 - I-V $\Rightarrow I_{\text{bias}}$ & I_{guard} & $U_{\text{breakdown}}$
 - AC cap values for all channels
 - test caps for breakdown by ramping up voltage across cap of up to 100V $\Rightarrow$ search for pinholes
 - bias/interstrip resistors
 - strip currents measured on samples
- results stored in traveler system and data base $\Rightarrow$ information used for production (e.g. bond skipping)




Evolution of depletion voltage

- wafer resistivity changes during production
- for a just-in-time production large fluctuations in characteristic depletion voltage made barrel assembly difficult

F-disk: also crystal orientation change (111)->(100)





90° sensors: large fluctuations in U_{depl} at end of production



Sensor problems

- each of our different sensor type had its own maladies ...
- 90° double-sided double-metal:
 - initially serious problems with fragile double metal layer
 - could be cured by increasing metal thickness





Measure $\frac{1}{2}$ of capacitance

p-stop isolation problem



- p-stops on n+ to provide strip isolation
- 90° sensors have combined p-stops (1 individual + 1 common frame)
- observed on some ladders high excess noise caused by a single strip
- strips had defects in individual p-implants
- careful visual scans did not catch this entirely, but single strip leakage measurements
- yield reduced considerably to ~35%
- problem could be partially traced back to mask defects

noise of strips




Sensor problems

- 2^o stereo sensors:
 - high values ($>10\text{ M}\Omega$) for the bias resistors R_{bias}
 - ✓ resulted in significant worsening of testing yield for some period of time
 - ✓ protective PECVD layer above polysilicon was missing, plasma etching caused high R_{bias} values
 - partially large inhomogeneity (50%) across strips for bias resistor R_{bias}
 - ✓ strips received non-uniform implanting
 - ✓ solved by outsourcing ion implanting



Current instabilities

- leakage current changes after probing p-side:
 - significant increase in current after probing appeared during several months and was a temporary phenomena
 - fortunately most of affected sensors went back to normal currents after several days/week
 - although investigated we could not clarify this effect nor make any conclusive link to processing





low interstrip resistance



- early sensors in 1998 had low interstrip resistances of few $k\Omega$ on p-side
 - probably caused by contaminations in the Nitrogen purge gas
 - mobile charge in oxide => loss of strip isolation ?
 - problem disappeared after additional purge gas was exchanged and additional cleaning/rinsing steps have been introduced
- this and the previous phenomena indicate that the oxide quality plays an important role and should be part of the QA process
 - we did not fully exploit measurement capabilities on teststructures e.g.
 - ✓ measure flatband shifts regularly on MOS structures
 - ✓ measure mobile oxide charge (Na^+) at elevated temperatures ...

Overall acceptance yield



- (our) acceptance yield of F-disk and 2°-sensors varied strongly over time, in average ~40-50%
- our testing yield at Fermilab of 90°-sensors improved steadily (note: this yield does not include Micron production yield: ~40%)



Chip/HDI



- use SVX11 chip (1.2 μ m CMOS)
 - preamplifier, 32-cell pipeline, 8 bit ADC and sparse readout
 - chips developed at FNAL/LBL and tested
- high density interconnect (HDI)
 - Kapton based flex circuit
 - our geometry required 9 different types !
 - fabrication/testing:
 - ✓ bare HDIs visual inspected and traces tested for shorts
 - ✓ laminated to Be-substrate and components mounted
 - ✓ HDI package tested and burnt-in



System test




- Set up and perform from early on a small scale system test
 - test the full R/O chain
 - detailed noise/timing studies of SVX and R/O boards
 - electronics integration
 - understanding of cabling, electronics and system problems
 - achieved tiny error rate of less than 10^{-14}
 - test turned to a real 10% system test when a full barrel/disk module was read out

system test was unbelievable crucial in getting the detector to work ...


QA during ladder construction

- laminated Be substrate on HDI glued on one side of silicon (HDI then wrapped over and glued to other side)
 - mechanical position of Be piece(s) w.r.t silicon targets crucial since it defines ladder position in barrel
 - assembly done under CMM control
 - remeasured several times during ladder construction and before insertion into barrel
 - achieved ladder accuracy of $\sim 5\mu\text{m}$ in-plane
 - ladder flatness (warps) $\sim 30\text{-}50\mu\text{m}$

align sensors with CMM
on fixtures




Check position of Be notches
and glue w/ epoxy on Silicon



QA on ladders: debug/repair

- immediately after assembly ladders were subject to a debugging/repair phase:
 - thorough visual inspection
 - test of grounding of Be substrate
 - ✓ causes bad pedestal structures, common mode shift $\Rightarrow$ indium solder/silver epoxy
 - look for remaining shorted pinholes by slowly applying $\pm$ HV on n/p-side
 - ✓ pull wirebonds



Bad ground connection

Bonds need to be plucked


QA on ladders: debug/repair



- however: had some damage during our complex assembly of ladders, repairs were necessary
 - ✓ ~20% of ladders did not download and/or had a chip/circuit problem
 - ✓ missing/ touching control bonds
 - ✓ damaged flex circuit pigtail
 - ✓ chips could be replaced on ladder
- tools available
 - ✓ dedicated debug/repair team (physicists + technicians)
 - ✓ stand alone DAQ test stands
 - ✓ probe stations
 - ✓ logic analyzer
- overall yield of repair work was ~85%

QA on ladders: HV

- $\pm$ HV curves were taken to determine leakage currents and micro discharge limit for p-side
 - currents for $\pm$ HV for double sided detectors quite different
 - breakdown on p-side appears earlier if AC-capacitor is held on GND



determine V_{-max} p-side breakdown voltage

important parameter for split bias operation


p-side breakdown/micro discharge



- With n side at ground and p side on negative potential we observed a burst-like noise, if the capacitors are ground. Observation is consistent with micro discharges at the edge of strips (as seen by KEK group KEK 93-129).
- steep increase in strip current and earlier junction breakdown
- effect correlates with misalignment of Al-strips and implant
- effect caused by field distortions and charge accumulation near the p-implant when p-side capacitor is grounded. Effect does not appear on the n+ strips
- we should expect that after irradiation and type inversion from n to p silicon the effect should be mitigated on the p side and moves to the n- side, where the junction is => **later**



Ladder QA: burn-in

- after debugging/repair ladders were subject to a burn-in run of up to 72h
 - data integrity check, multiple downloads
 - pedestals/noise
 - gain per channel
 - test sparse readout
 - long term HV voltage operation (cooled) => currents







Ladder QA: laser test

- test ladder after burn-in on laser stand(s)
 - 1064 nm laser light
 - traverses 300 μ m Si
- goals:
 - measure charge collection efficiency and depletion voltage
 - complete scan across strip
 - ✓ check homogeneity
 - ✓ check dead channels




Ladder QA: grading

- grading system for ladders:
 - mechanical accuracy
 - # of noisy strips from burn-in
 - # of dead channels from laser
 - leakage current & $V_{\max}$
 - ✓ grade A: less than 2.6% dead+noisy (10 per $3 \times 128 = 384$ strips channels)
 - ✓ grade B: less than 5.2% dead+noisy channels




Radiation test

- carried out a new irradiation test with 8GeV p at Fermilab booster in Feb/Mar 2001
- irradiated ladders up to 2.1 MRad in 5 steps (~min 4 years Run I Ia in inner layer)
- depletion voltage of most ladder types agree, except 90°-sensor ladder (double-metal) ... unclear ??




Radiation test

- also stronger increase in average noise on n-side for double-metal detector after irradiation
- observe temperature dependence of n-side noise:
 - the lower the Temperature, the earlier the noise occurs
 - mobility changes $\mu \sim T^{-2.3} \Rightarrow$ earlier junction breakdown



p-side noise (not shown) was immune against this effect. A hint that micro discharge has moved from P-side to n-side ??



Conclusions



- DØ silicon tracker has been built and is working (first tracks seen)
- production was a huge effort of many people, although only 3.2m² silicon area
- had tight QA measures at different stages of the fabrication process in place
 - sensors: thorough testing, quick feedback to vendor and local presence turned out to be crucial
 - ladders: multi-layer quality control (debug, burn-in, laser) with dedicated repair/debug teams and clear procedures was important
 - system test from early on helped us enormously
- however: much bigger logistical enterprise than originally anticipated:
 - too many detector types with too many single components with too many different vendors with too many delivery problems
- double-sided detectors may not be worth it: only moderately radiation hard