

Surface related QA parameters

Conclusions

- how surface parameters affect the sensor is design dependent
- surface parameters are process dependent
- standardized monitor structures necessary for QA+QC
 - input for device simulations
 - radiation induced effects